

Mondi Štětí a.s.  
Litoměřická 272  
CZ - 411 08, Štětí  
[www.mondigroup.com](http://www.mondigroup.com)

## **Vulcan S100 Installation**

To the Kostečka Team,

The Vulcan device is installed on lime oven, which usually required extensive scale cleaning every 3 months. It has now been 4 months since installation of the Vulcan S100, and the scale problem have reduced significantly.

Now the pipes and production equipment require much less cleaning. We are very satisfied with the performance of the Vulcan S100 Unit.

Best Regards,

The Mondi Group



Mondi Štětí a.s manufacturing plant in the Czech Republic



Deposit removed from pipe after Vulcan installation



Vulcan S100



Installation of Vulcan S100 on lime kiln

